

# VEHICLE INSPECTION REPORT

**SJ15TZL**

## Vauxhall Vivaro 2900 1.6CDTI 115PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 25/03/2015

Year 2015

Mileage 83,614 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN W0L3F7018FV625208

Body Style Panel Van LWB

Keys 2

MOT Due 28/11/2025

CAP Clean £3,000.00

CAP Average £2,475.00

CAP Below £1,800.00

Gearbox MANUAL

Gears 6

Doors 2

Steering Combi Standard Axle

Rear Suspension Steel

SINGLE SIDE DOOR

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Bonnet  
Dented  
With Paint Damage




3: Wing osf  
Rusted  
Over 5mm



4: Door osf  
Dented  
With Paint Damage



5: Tailgate  
Dented  
With Paint Damage



6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Door nsr  
Dented  
With Paint Damage

## Interior

Carpet Condition		Upholstery Condition	
Seat Condition	OK Average	Odour	OK No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK