

VEHICLE INSPECTION REPORT

G120AK

Man TGM 18.240

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 17/11/2007

VIN WMAN18ZZ88Y200479

Axle Combi 4x2

Year 2007

Body Style Horsebox

Rear Suspension Steel

Mileage 331,690 Km Not Warranted

MOT Due 30/04/2026

Tail Lift Column

Fuel Type Diesel

Cab Type L CAB

Colour BLACK

Gearbox AUTOMATIC

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm



2: Bumper Front
Cracked
UpTo 25mm



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Other
N/A
N/A



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Other
N/A
N/A



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Panel Rear
Scratched
UpTo 25mm Thru Paint



11: Qtr Panel osr
Hole
Over 10mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door osf
Scratched
Over 25mm Not Thru Paint



16: Door Mirror Assy osf
Broken
Replace



17: Other
N/A
N/A



18: Seat Base Cover osf
Burn
Over 3mm



19: Seat Back Cover osf
Burn
Over 3mm



20: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	