

VEHICLE INSPECTION REPORT

PN17HZE

Daf LF 260

| Non | Runner |
|--------|--------|
| Inenec | tion |

Vehicle

| Serious Damage? | No | VAT | Plus VAT |
|-----------------|----|-----|----------------|
| | | V5 | Buyer To Apply |

Details

| Reg. date | 10/04/2017 | VIN | XLRAEL3700L462691 | Rear Suspension |
|-----------|----------------|------------|-------------------|-----------------|
| Year | 2017 | Body Style | Curtainside | Rear Doors |
| Mileage | 634,282 Km Not | Cab Type | DAY CAB | Tail Lift |
| - | Warranted | Gearbox | MANUAL | |
| Fuel Type | Diesel | Axle Combi | 4x2 | - |
| Colour | WHITE | | | - |

NON RUNNER - NO GEARBOX

Tyres

| NSF | NSI1 | NSI2 | NSI3 | NSI4 |
|-------|------|------|------|------|
| OSF | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
| | OS01 | OSO2 | OS03 | OSO4 |

Features

- Bluetooth connection
 Central locking
- Cruise control
 Cloth seat trim
 - Digital radio
- Front electric windows

Steel

Roller

Tuckaway

Photos

























Condition Check



Damage Photos



1: Unclassified Major Parts Missing Report Only



2: Panel Front Scratched Over 25mm Thru Paint



3: Screen Front Cracked Replace



4: Panel Front Scratched Over 25mm Thru Paint



5: Bumper Front Dented With Paint Damage



6: Bumper Front Moulding Broken Replace



7: Unclassified Major Parts Missing Report Only



8: Qtr Panel nsr Hole Over 10mm



9: Door osf Scratched Over 25mm Thru Paint



10: Wing osf Scratched Over 25mm Thru Paint



11: Door Pad osf Soiled Heavy



12: Fascia Panel Missing Replace

Interior

Carpet ConditionOKUpholstery ConditionPoorSeat ConditionOKOdour-Engine RunsFault