

# VEHICLE INSPECTION REPORT

**FG65JWO**

## Mercedes-Benz Antos 1842

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	26/01/2016	Colour	WHITE	Cab Type	DAY CAB
Year	2016	VIN	WDB9630032L977816	Gearbox	AUTOMATIC
Mileage	295,557 Km Warranted	Body Style	Vacuum Excavator	Axle Combi	4x2
Fuel Type	DIESEL	MOT Due	31/03/2026	Rear Suspension	Steel

SURROUND CAMERA SYSTEM, RSP ESE18/4-L BODY (YEAR 2015)

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Broken  
Replace



2: Fog Lamp Surround is  
Scuffed (Unpainted)  
Up To 100mm





3: Fog Lamp Surround ns  
Scuffed (Unpainted)  
UpTo 100mm



4: Door Mirror Assy nsf  
Missing  
Replace



5: Door nsf  
Scratched  
UpTo 25mm Thru Paint



6: Other  
N/A  
N/A



7: Door osf  
Scratched  
UpTo 25mm Thru Paint



8: Other  
N/A  
N/A



9: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK