

VEHICLE INSPECTION REPORT

GN65NCO

Daf CF 290

Non Runner Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	01/10/2015	VIN	XLRASM4100G055182	Rear Suspension	Air
Year	2015	Body Style	Box Van	Rear Doors	Roller
Mileage	422,722 Km Not	Cab Type	SLEEPER CAB	Tail Lift	Column
	Warranted	Gearbox	AUTOMATIC		
Fuel Type	Diesel	Axle Combi	6x2		
Colour	WHITE				

*PROP SHAFT CENTRE BEARING BROKEN*WARNING LIGHT ON DASH* CARRIER SUPRA 1150MT UNIT, STANDBY PLUG, TWIN EVAP, SEPARATOR, REAR LIFT

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	

Features

- Bluetooth connection
- Front electric windows
 Central locking
- Cruise control
 Central locking
- Digital radioCloth seat trim
- Air conditioning

Photos



















Condition Check



Damage Photos



1: Bumper Front Scratched Over 100mm Thru Paint



2: Panel Front Cracked Replace



3: Bonnet Scratched Over 25mm Thru Paint



4: Bumper Front Dented With Paint Damage



5: Door nsf Scratched Over 25mm Thru Paint



6: Wing nsf Scratched Over 25mm Thru Paint



7: Qtr Panel nsr Scratched Over 25mm Thru Paint



8: Unclassified Major Parts Missing Report Only



9: Qtr Panel nsr Cracked Replace



10: Qtr Panel osr Scratched Over 25mm Thru Paint



11: Door osf Dented With Paint Damage



12: Door osf Scratched Over 25mm Thru Paint



13: Wing osf Scratched Over 25mm Thru Paint



14: Door Pad osf Broken Replace



15: Seat Base Cover osf Torn Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs		Fault	