

VEHICLE INSPECTION REPORT

YB15OHL

Mercedes-Benz Actros 1840

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	30/06/2015	Colour	GREEN	Cab Type	CLASSICSPACE CAB
Year	2015	VIN	WDB9634032L957378	Gearbox	AUTOMATIC
Mileage	747,000 Km Warranted	Body Style	Tractor Unit	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/10/2025	Rear Suspension	Air

SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Cruise control
- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Broken
Replace



3: Door osf
Dented
With Paint Damage



4: Door osf
Dented
Over 30mm



5: Door osf
Scratched
Over 25mm Thru Paint



6: Door Pad osf
Soiled
Heavy



7: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		