

VEHICLE INSPECTION REPORT

NK15ZVD

Scania P 250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	27/03/2015	VIN	YS2P4X20005378546	Gearbox	AUTOMATIC
Year	2015	Body Style	Fridge Box	Axle Combi	4x2
Mileage	744,353 Km Warranted	Service history	Yes	Rear Suspension	Air
Fuel Type	Diesel	MOT Due	30/11/2025	Rear Doors	Roller
Colour	WHITE	Cab Type	DAY CAB	Tail Lift	Column

THERMO KING T-1000R UNIT, SEPARATOR

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Hole
Over 10mm



2: Bumper Front
Cracked
Over 25mm



3: Panel Front
Scratched
Over 25mm Thru Paint



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: B Post os
Scratched
Over 25mm Thru Paint



8: Door osf
Scratched
Over 25mm Thru Paint



9: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		