

VEHICLE INSPECTION REPORT

DG18CVD

Isuzu N75 190

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 07/03/2018

VIN JAANPR75MH7100592

Axle Combi 4x2

Year 2018

Body Style Dropside

Rear Suspension Steel

Mileage 357,807 Km Warranted

MOT Due 31/05/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour BLUE/YELLOW

Gearbox AUTOMATIC

WARNING LIGHT ON DASH SURROUND CAMERA SYSTEM, SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Door Mirror Assy nsf
Missing
Replace



2: Door nsf
Dented
Over 30mm



3: Door osf
Dented
With Paint Damage

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
Parking Brake		OK		No Excessive Smoking		OK	
EML light illuminated		Fault		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	