

VEHICLE INSPECTION REPORT

EG66APK

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 31/01/2017

Year 2017

Mileage 162,371 Miles
Warranted

Fuel Type DIESEL

Colour WHITE

VIN WDB9066332P310278

Body Style Panel Van MWB

MOT Due 06/02/2026

CAP Clean £3,825.00

CAP Average £3,250.00

CAP Below £2,475.00

Gearbox MANUAL

SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



2: Qtr Panel nsr
Rusted
Over 5mm



3: Qtr Panel nsr
Rusted
Over 5mm



4: Qtr Panel osr
Rusted
Over 5mm



5: Qtr Panel osr
Rusted
Over 5mm



6: D Post os
Rusted
Over 5mm

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK