

VEHICLE INSPECTION REPORT

ND67CXB

Mercedes-Benz Sprinter 314 Cdi

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/11/2017

Year 2017

Mileage 106,712 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9066332P503628

Body Style Panel Van MWB

Keys 1

MOT Due 02/03/2026

CAP Clean £5,000.00

CAP Average £4,225.00

CAP Below £3,225.00

Gearbox MANUAL

Doors 2

Steering Combi Standard Axle

Rear Suspension Steel

RECALL OUTSTANDING

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Roof
Rusted
Over 5mm



4: Bonnet
Dented
With Paint Damage



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Door osf
Dented
Over 30mm



7: B Post os
Rusted
Over 5mm



8: Qtr Panel osr
Rusted
Over 5mm



9: Badgedecal Rear
Broken
Replace



10: Tailgate
Dented
With Paint Damage



11: Bumper Rear Moulding
Broken
Replace



12: Qtr Panel nsr
Rusted
Over 5mm



13: Door nsr
Dented
Over 30mm



14: Door nsr
Dented
Over 30mm



15: Wing nsf
Rusted
Over 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK