

# VEHICLE INSPECTION REPORT

**DG66JUV**

## Mercedes-Benz Actros 2545

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date	20/12/2016	Colour	WHITE	Gearbox	AUTOMATIC
Year	2016	VIN	WDB96342320111863	Axle Combi	6x2
Mileage	998,480 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	Cab Type	STREAMSPACE CAB (2.5M, FLAT FLOOR)	Rear Suspension	Air

\*WARNING LIGHT ON DASH\*RADIATOR LEAKING\* SLIDING 5TH WHEEL

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Digital radio
- Central locking

## Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Cracked  
Over 25mm





3: Door nsf  
Scratched  
Over 25mm Not Thru Paint



4: Door Moulding nsf  
Scratched (Painted)  
Over 25mm Thru Paint



5: Qtr Panel Moulding os  
Missing  
Replace



6: Aperture Seal osf  
Broken  
Replace



7: Screen Front  
Chipped  
Over 10mm



8: Door Pad osf  
Soiled  
Heavy

## Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	Fault		