

VEHICLE INSPECTION REPORT

WN12BFM

Mercedes-Benz Sprinter 513

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		•	

Details

Reg. date	30/03/2012	VIN	WDB9066532S670351	Cab Type	DAY CAB
Year	2012	Body Style	Access Platform	Gearbox	MANUAL
Mileage	156,162 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	WHITE	MOT Due	30/04/2026		

OUTSTANDING RECALL, WARNING LIGHT ON DASH

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	_

Features

- Bluetooth connectionRadio/CDCentral locking

- Cruise control Front electric windows • Cloth seat trim
- Park assist camera
- Drivers airbag
- Rear parking sensorPassenger airbag

Photos





































Condition Check



Damage Photos



1: Roof Chipped Multiple Chips



2: Bonnet Chipped Multiple Chips



3: Bumper Front Dented With Paint Damage



4: Wing nsf Dented Over 30% Of Panel



5: B Post ns Dented With Paint Damage



6: Qtr Panel nsr Dented With Paint Damage



7: Qtr Panel nsr Scratched Over 25mm Thru Paint



8: Qtr Panel nsr Rusted Over 5mm



9: Qtr Panel nsr Dented With Paint Damage



10: Qtr Panel osr Dented Over 30mm



11: Qtr Panel osr Scratched Over 25mm Thru Paint



12: Qtr Panel osr Dented Over 30mm



13: Qtr Panel osr Rusted Over 5mm



14: Qtr Panel osr Dented With Paint Damage



15: Door osf Dented With Paint Damage



16: B Post os Rusted Over 5mm



17: Wing osf Dented Over 30% Of Panel



18: Bumper Front Scratched Over 100mm Thru Paint



19: Carpets Front Holed Over 3mm



20: Door Pad osf Soiled Heavy



21: Seat Base Cover osf Scuffed Over 25mm



22: Seat Base Cover nsf Soiled Heavy



23: Door Pad nsf Soiled Heavy

Interior

Carpet Condition Seat Condition	Poor Poor		Upholstery Condition Odour	Poor -	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	minated	Fault