

VEHICLE INSPECTION REPORT

OU15ZVF

MAN NEOPLAN TOURLINER COACH

Non Runner Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
Details			
Reg. date	14/05/2015	VIN	WAGP22ZZ3FT022331 Axle Combi

6x2 Year 2015 Coach Steering Combi Steer **Body Style** Mileage Not Showing **Rear Suspension** Air Keys **Fuel Type** Gearbox **AUTOMATIC** Diesel WHITE Colour **Doors** 3

5% BUYERS FEE *NON-RUNNER - DOESNT START OR DRIVE* *CRACKED WINDSCREEN* 61 SEAT CAPACITY (4 SEATS MISSING), 57 WITH WHEELCHAIR ACCESS, WHEELCHAIR LIFT, TOILET, FABRIC SEATS, 3 PT SEATBELTS, FULL WIDTH UNDERBODY STORAGE, OVERHEAD STOWAGE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OS01	OSO2	OSO3	OS04

Features

Bluetooth connection

• Radio/CD

• Cloth seat trim

Photos



















Condition Check



Damage Photos



1: Bonnet Missing Replace



2: Bumper Front Missing Replace



3: Qtr Panel osr Rusted Over 5mm



4: Bumper Rear Cracked Over 25mm



5: Qtr Panel nsr Dented With Paint Damage



6: Headlamp ns Missing Replace



7: Headlamp os Missing Replace

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average -	
Engine Runs		Fault	Gearbox 1st and Reverse	e Test	Fault
Brakes		Fault	Clutch Slip Test from Sta	tic	Fault
Turbo Boosting		Fault	Gearbox Static Gear Sele	ection (engine running)	Fault
Parking Brake		Fault	No Excessive Smoking		Fault
EML light illuminated		Fault	Oil warning light illuminat	ed	Fault
Airbag light illuminated Fault		DPF light illuminated		Fault	
ABS light illuminated		Fault	Service indicator light illu	minated	Fault
Windows		OK	Radio		OK