

VEHICLE INSPECTION REPORT

NL69ETD

Scania G 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 01/12/2019

VIN YS2G6X20005571208

Gearbox AUTOMATIC

Year 2019

Body Style Tractor Unit

Axle Combi 6x2

Mileage 778,954 Km Warranted

Service history Yes

Steering Combi Mid-Lift

Fuel Type DIESEL

MOT Due 30/09/2025

Rear Suspension Air

Colour WHITE

Cab Type NORMAL SLEEPER
CAB

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Navigation system
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Up To 100mm



2: Wing osf
Chipped
1 To 5



3: Wing nsf
 Scratched
 UpTo 25mm Not Thru Paint



4: Door Mirror Assy nsf
 Scuffed (Unpainted)
 UpTo 100mm



5: Door nsf
 Scratched
 Over 25mm Thru Paint



6: Qtr Panel nsr
 Scratched
 UpTo 25mm Thru Paint



7: Other
 N/A
 N/A



8: Other
 N/A
 N/A



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



10: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	