

VEHICLE INSPECTION REPORT

RE69TMX

Ford Transit 350 2.0 ECOBLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 22/11/2019

Year 2019

Mileage 158,332 Miles Not Warranted

Fuel Type DIESEL

Colour WHITE

VIN WF0EXXTTREKS16061

Body Style Panel Van L3

MOT Due 26/11/2025

CAP Clean £3,950.00

CAP Average £3,450.00

CAP Below £2,775.00

Gearbox MANUAL

Gears 6

WARNING LIGHTS ON DASH AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Front parking sensor
- Rear parking sensor
- Digital radio
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Wing of
Dented
Between 10mm + 30mm



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips



4: Front TowEye Cvr
Missing
Replace



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Other
N/A
N/A



7: Wing nsf
Scratched
Over 25mm Not Thru Paint



8: Door Mirror Assy nsf
Broken
Replace



9: Door Mirror Glass ns
Broken
Replace



10: Moulding nsf Wing
Broken
Replace



11: Door nsf
Dented
Between 10mm + 30mm



12: Other
N/A
N/A



13: Screen Front
Cracked
Replace



14: Sill ns
Dented
With Paint Damage



15: Door nsr
Scratched
Over 25mm Not Thru Paint



16: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



17: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



18: Qtr Panel Moulding ns
Scuffed (Unpainted)
UpTo 100mm



19: Qtr Panel Arch Extension ns
Broken
Replace



20: Qtr Panel Trim ns
Scuffed
Over 25mm



21: Bumper Rear Moulding
Broken
Replace



22: Bumper Rear
Insecure
Action Required



23: Door nsr
Dented
Between 10mm + 30mm



24: Door osr
Dented
With Paint Damage



25: Lamp nsr
Broken
Replace



26: Lamp osr
Broken
Replace



27: Bumper Rear Moulding
Broken
Replace



28: Panel Rear
Dented
Between 10mm + 30mm



29: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



30: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



31: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



32: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



33: Qtr Panel osr
Dented
With Paint Damage



34: Door osf
Dented
Between 10mm + 30mm



35: Door osf
Dented
With Paint Damage



36: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



37: Moulding osf Wing
Scuffed (Unpainted)
UpTo 100mm



38: Flasher Side Repeater os
Broken
Replace



39: Other
N/A
N/A

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK