

# VEHICLE INSPECTION REPORT

**DG17WZC**

## Man TGS 26.360

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

|           |                      |            |                   |                 |         |
|-----------|----------------------|------------|-------------------|-----------------|---------|
| Reg. date | 30/08/2017           | Colour     | BLUE              | Cab Type        | DAY CAB |
| Year      | 2017                 | VIN        | WMA18SZZXHY364047 | Gearbox         | MANUAL  |
| Mileage   | 205,868 Km Warranted | Body Style | Dropside & Crane  | Axle Combi      | 6x2     |
| Fuel Type | DIESEL               | MOT Due    | 30/09/2025        | Rear Suspension | Air     |

\*PTO DOES ENGAGE BUT LEGS WILL NOT COME DOWN\* HMF 1420K-RC REMOTE CRANE (YEAR 2017)  
SURROUND CAMERA SYSTEM, SERVICE SCHEDULE LIST AVAILABLE

### Tyres

|       |      |      |      |      |
|-------|------|------|------|------|
| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |

## Features

- Park assist camera

## Photos










## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
Multiple Chips



2: Fog Lamp Surround os  
Scuffed (Unpainted)  
Over 100mm



3: Screen Front  
Chipped  
UpTo 10mm



4: Fog Lamp Surround ns  
Scuffed (Unpainted)  
Over 100mm



5: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



6: Other  
N/A  
N/A



7: Door nsf  
Chipped  
Multiple Chips



8: Other  
N/A  
N/A





9: Other  
N/A  
N/A



10: Bumper Rear  
Dented  
Between 10mm + 30mm



11: Other  
N/A  
N/A



12: Door osf  
Scratched  
UpTo 25mm Thru Paint



13: Door osf  
Chipped  
Edge Chip



14: Other  
N/A  
N/A



15: Seat Base Cover osf  
Torn  
Over 3mm

Interior

| Carpet Condition         |  | Average |  | Upholstery Condition                           |  | Average |  |
|--------------------------|--|---------|--|--|--|---------|--|
| Seat Condition           |  | Average |  | Odour  |  | -       |  |
| Engine Runs              |  | OK      |  | Gearbox 1st and Reverse Test                   |  | OK      |  |
| Brakes                   |  | OK      |  | Clutch Slip Test from Static                   |  | OK      |  |
| Parking Brake            |  | OK      |  | Gearbox Static Gear Selection (engine running) |  | OK      |  |
|                          |  |         |  | No Excessive Smoking                           |  | OK      |  |
| EML light illuminated    |  | OK      |  | Oil warning light illuminated                  |  | OK      |  |
| Airbag light illuminated |  | OK      |  | DPF light illuminated                          |  | OK      |  |
| ABS light illuminated    |  | OK      |  | Service indicator light illuminated            |  | OK      |  |