

VEHICLE INSPECTION REPORT

NK15ZVA

SCANIA P 250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	14/04/2015	Body Style	Fridge Box	Axle Combi	4x2
Year	2015	Service history	Yes	Rear Suspension	Air
Mileage	862,933 Km Warranted	Service documents	Printout	Rear Doors	Roller
Fuel Type	Diesel	MOT Due	30/09/2025	Tail Lift	Column
Colour	WHITE	Cab Type	DAY CAB		
VIN	YS2P4X20009194620	Gearbox	AUTOMATIC		

MOT HISTORY INCORRECTLY RECORDED IN MILES/KM THERMOKING SPECTRUM 1000R UNIT

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Central locking
- Park assist camera
- Cloth seat trim
- Radio/CD
- Front electric windows


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bonnet
Hole
Over 10mm



3: Bumper Front
Cracked
Over 25mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		