Rear Suspension

Steel



VEHICLE INSPECTION REPORT

Vehicle

MOT Due

DK67VTY

Man TGM 18.250

DIESEL

Inspection

Serious Damage?	No	VAT	Plus VAT		
		V5	To Follow		
Details					
Reg. date	15/09/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMAN08ZZ4HY364718	Gearbox	MANUAL
Mileage	169,306 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2

31/07/2026

SERVICE SCHEDULE LIST AVAILABLE, HMF 1420K-RC REMOTE CRANE (YEAR 2017), SURROUND CAMERA SYSTEM

Tyres

Fuel Type

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	_
	OS01	OS02	OS03	OSO4	

Features

Park assist camera

Photos

















Condition Check



Damage Photos



1: Other N/A N/A



2: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



3: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



4: Wing nsf Scratched UpTo 25mm Thru Paint



5: Other N/A N/A



6: Other N/A N/A



7: Door Mirror Assy nsf Broken Replace



8: Bumper Rear Rusted Over 5mm



9: Other N/A N/A



10: Door osf Scratched UpTo 25mm Thru Paint



11: Door osf Chipped Edge Chip



12: Seat Base Cover osf Holed Over 3mm



13: Door Pad osf Broken Replace

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average -	
Engine Runs		OK	Gearbox 1st and Revers	se Test	OK
Brakes		OK	Clutch Slip Test from St	atic	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ated	OK
Airbag light illuminated	ı	OK	DPF light illuminated		OK
ABS light illuminated OK		Service indicator light illuminated		OK	