

# VEHICLE INSPECTION REPORT

**DG680FN**

## Mercedes-Benz Sprinter 314 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 07/09/2018

Year 2018

Mileage 132,212 Miles  
Warranted

Fuel Type DIESEL

Colour WHITE

VIN WDB9061332N732907

Body Style Dropside MWB

MOT Due 06/09/2025

CAP Clean £5,300.00

CAP Average £4,550.00

CAP Below £3,550.00

Gearbox MANUAL

Tail Lift Column

\*BROKEN DPF\*

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Park assist camera
- Front electric windows
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
UpTo 25mm Thru Paint



2: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



3: Wing nsf  
Dented  
2 Or Less UpTo 10mm



4: Door Mirror Assy nsf  
Broken  
Replace



5: Door nsf  
Dented  
With Paint Damage



6: Door nsf  
Dented  
With Paint Damage



7: Door nsf  
Dented  
Over 30mm



8: Door nsf  
Chipped  
Multiple Chips





9: B Post ns  
Chipped  
Multiple Chips



10: Door Moulding nsf  
Scuffed (Unpainted)  
UpTo 100mm



11: Other  
N/A  
N/A



12: Other  
N/A  
N/A



13: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm



14: Door Moulding osf  
Scuffed (Unpainted)  
UpTo 100mm



15: Sill os  
Scratched  
Over 25mm Thru Paint



16: Other  
N/A  
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	