

VEHICLE INSPECTION REPORT

PO70KKN

Fiat Ducato 35 2.3 MULTIJET 140PS

Serious Damage?	No	VAT	Plus VAT		
		V5	To Follow	- -	
Details					
Reg. date	22/09/2020	VIN	ZFA25000002N88062	CAP Below	£5,750.00
Year	2020	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	78,700 Miles Warranted	MOT Due	08/10/2025	Gears	6
		CAP Clean	£7,850.00		
Fuel Type	DIESEL	CAP Average	£7,025.00	-	
Colour	WHITE		,	-	

^{*}WARNING LIGHT ON DASH* AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Vehicle

ı	y١	re	S
		_	

Inspection

NSF

NSR

OSF

OSR Spare

Features

Navigation system

· Park assist camera

· Air conditioning

· Front electric windows

Photos

















Condition Check



Damage Photos



1: Wing osf Dented With Paint Damage



2: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



3: Screen Front Chipped UpTo 10mm



4: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



5: Wing nsf Scratched UpTo 25mm Thru Paint



6: Door Mirror Assy nsf Broken Replace



7: Flasher Side Repeater ns Missing Replace



8: Door Mirror Glass ns Broken Replace



9: Sill ns Dented Between 10mm + 30mm



10: Door nsf Scratched Over 25mm Thru Paint



11: B Post ns Dented With Paint Damage



12: Other N/A N/A



13: Door nsr Scratched UpTo 25mm Thru Paint



14: Other N/A N/A



15: Sill ns Dented With Paint Damage



16: Qtr Panel nsr Scratched UpTo 25mm Thru Paint



17: Qtr Panel nsr Dented Between 10mm + 30mm



18: Qtr Panel Moulding ns Scuffed (Unpainted) UpTo 100mm



19: Bumper Rear Moulding Scuffed (Unpainted) UpTo 100mm



20: Bumper Rear Moulding Scuffed (Unpainted) UpTo 100mm



21: Qtr Panel Moulding os Broken Replace



22: Door Mirror Assy osf Broken Replace



23: Flasher Side Repeater os Broken Replace



24: Door Mirror Glass os Missing Replace



25: Door osf Dented With Paint Damage



26: Sill os Scratched Over 25mm Thru Paint



27: Carpets Front Holed Over 3mm

Interior

Carpet Condition Seat Condition	Average Average			verage Io	
Engine Runs		OK	Gearbox 1st and Reverse To	est	OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selecti	on (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		Fault	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illumin	nated	OK