

VEHICLE INSPECTION REPORT

WN12BFJ

MERCEDES-BENZ SPRINTER

Serious Damage?	No	VAT	Plus VAT	
		V5	Present	
Details				
Dan data	20/02/2042	Colour	\A/I IITE	

Vehicle

Reg. date	30/03/2012	Colour	WHITE	Сав Туре	DAY CAB
Year	2012	VIN	WDB9066532S670348	Gearbox	MANUAL
Mileage	188,459 Km Warranted	Body Style	Access Platform	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/06/2026	Rear Suspension	Steel

OUTSTANDING RECALL, MOT HISTORY INCORRECTLY RECORDED IN MILES/KM VERSALIFT ET36NF (YEAR 2012)

Tyres

Inspection

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	_
	OS01	OSO2	OSO3	OSO4	

Features

- Bluetooth connection
- · Front electric windows
- Cloth seat trim
- Cruise control
- · Drivers airbag
- Park assist camera
- Passenger airbag
- Digital radio
- Central locking

Photos
































Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Panel Front Dented With Paint Damage



3: Bumper Front Scratched Over 100mm Thru Paint



4: Wing nsf Poor Previous Repair Poor Paint



5: Wing nsf Dented With Paint Damage



6: Door Mirror Assy nsf Broken Replace



7: Door nsf Chipped Multiple Chips



8: Qtr Panel nsr Dented With Paint Damage



9: Qtr Panel osr Dented With Paint Damage



10: Bumper Rear Moulding Scuffed (Unpainted) Over 100mm



11: Qtr Panel Moulding os Scuffed (Unpainted) Over 100mm



12: Qtr Panel osr Dented With Paint Damage



13: Qtr Panel osr Dented Over 30mm



14: Qtr Panel Moulding os Scuffed (Unpainted) Over 100mm



15: Qtr Panel osrDentedWith Paint Damage



16: Qtr Panel osr Dented Over 30mm



17: Qtr Panel osr Rusted Over 5mm



18: Qtr Panel osr Dented Over 30mm



19: B Post os Rusted Over 5mm



20: Door osf Dented With Paint Damage



21: Door osf Dented With Paint Damage



22: Door Pad osf Soiled Heavy



23: Carpets Front Soiled Heavy



24: Seat Base Cover osf Torn Over 3mm



25: Seat Base Cover nsf Soiled Heavy

Interior

Carpet Condition	Poor	Upholstery Condition Poor	
Seat Condition	Poor	Odour -	
Engine Runs		OK No Excessive Smoking	OK
EML light illuminated		OK DPF light illuminated	OK
ABS light illuminated		OK	