

# VEHICLE INSPECTION REPORT

**YA17SVJ**

## Daf CF 330

### Inspection

### Vehicle

VAT	Plus VAT
V5	Present

### Details

Reg. date	27/07/2017	VIN	XLRASM4100G147609	Gearbox	MANUAL
Year	2017	Body Style	Dropside & Crane	Axle Combi	6x2
Mileage	252,793 Km Warranted	Keys	1	Steering Combi	Rear-Lift Steer
Fuel Type	Diesel	MOT Due	31/07/2026	Rear Suspension	Air
Colour	BLUE	Cab Type	DAY CAB		

HMF 1420 K (2 EXT) REMOTE CRANE (YEAR 2017)


### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- Drivers airbag
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



3: Wing nsf  
Chipped  
Multiple Chips



4: Wing osf  
Cracked  
Replace



5: Door Moulding osf  
Scuffed (Unpainted)  
Over 100mm



6: Door osf  
Dented  
With Paint Damage



7: Qtr Panel osr  
Rusted  
Over 5mm



8: Tailgate  
Rusted  
Over 5mm





9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Door nsf  
Dented  
Over 2 UpTo 10mm



11: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm

### Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK