

VEHICLE INSPECTION REPORT

WV65OKL

Scania P 370

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	20/11/2015	Colour	WHITE	Cab Type	DAY CAB
Year	2015	VIN	YS2P8X40002112873	Gearbox	AUTOMATIC
Mileage	265,388 Km Warranted	Body Style	Refuse Collector	Axle Combi	8x4
Fuel Type	DIESEL	MOT Due	31/10/2025	Rear Suspension	Steel

WARNING LIGHT ON DASH, MILEAGE RECORDED IN KM & MILES ON MOT HISTORY SURROUND CAMERA SYSTEM, FRONT LOADER

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Missing
Replace



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Number Plate Front
Missing
Replace



4: Other
N/A
N/A



5: Door Mirror Assy nsf
Broken
Replace



6: Other
N/A
N/A



7: Other
N/A
N/A



8: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Number Plate Rear
Missing
Replace



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



14: Other
N/A
N/A



15: Other
N/A
N/A

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	