

VEHICLE INSPECTION REPORT

DG16DWE

Man TGS 26.360

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 19/04/2016

VIN WMA18SZZ3GW214470

Axle Combi 6x2

Year 2016

Body Style Flatbed

Steering Combi Rear-Lift Steer

Mileage 358,559 Km Warranted

MOT Due 31/12/2025

Rear Suspension Air

Fuel Type DIESEL

Cab Type DAY CAB

Colour BLUE

Gearbox MANUAL

SERVICE SCHEDULE LIST AVAILABLE, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Fog Lamp Surround os
Scuffed (Unpainted)
Over 100mm



3: Bumper Front Moulding
Broken
Replace



4: Bonnet
Chipped
1 To 5



5: Screen Front
Cracked
Replace



6: Wing nsf
Scratched
UpTo 25mm Thru Paint



7: Fog Lamp Surround ns
Scuffed (Unpainted)
Over 100mm



8: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



9: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



10: Door Mirror Assy nsf
Broken
Replace



11: Other
N/A
N/A



12: Door nsf
Scratched
UpTo 25mm Thru Paint



13: Other
N/A
N/A



14: Other
N/A
N/A



15: Bumper Rear
Rusted
Over 5mm



16: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Other
N/A
N/A



19: Door osf
Chipped
Edge Chip



20: Other
N/A
N/A



21: Other
N/A
N/A



22: Handle Inner osf
Damaged
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	