

VEHICLE INSPECTION REPORT

PE24UOF

Isuzu Gafter N35.125

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 10/05/2024

Year 2024

Mileage 19,040 Miles Not Warranted

Fuel Type DIESEL

Colour WHITE

VIN JAANLR87HM7103696

Body Style MOBILE DISPLAY UNIT

MOT Due 09/05/2027

Gearbox AUTOMATIC

AD BLUE, SPARE WHEEL, GENERATOR ON BOARD

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
UpTo 25mm Thru Paint



2: Screen Front
Cracked
Replace



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault