

VEHICLE INSPECTION REPORT

BX06LBG

Daf LF 45.170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/04/2006

Year 2006

Mileage 1,163,117 Km Not Warranted

Fuel Type DIESEL

Colour WHITE

VIN XLRAE45BF0L318522

Body Style Curtainside

MOT Due 31/12/2025

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Rear Doors Barn

Tail Lift Tuckaway

CLUTCH ISSUES

Tyres


NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Wing nsf
Cracked
Replace



6: Door Mirror Assy nsf
Missing
Replace



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Flasher Side Repeater ns
Broken
Replace



11: Bumper Rear
Rusted
Over 5mm



12: Other
N/A
N/A



13: Other
N/A
N/A



14: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



15: Other
N/A
N/A



16: Other
N/A
N/A



17: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK