

# **VEHICLE INSPECTION REPORT**

**BE11MKM** 

### **Iveco Stralis 310**

No

Diesel

		V5	Present		
Details					
Reg. date	01/02/2019	Colour	YELLOW	Cab Type	DAY CAB
Year	2019	VIN	WJME62RN70C395370	Gearbox	AUTOMATIC
Mileage	255,484 Km Not Warranted	Body Style	Dropside & Crane	Axle Combi	6x2
		MOT Due	31/08/2026	Rear Suspension	Air

Plus VAT

#### REAR LIFT, ATLAS 135.2VE-A12 REMOTE CRANE (YEAR 2018)

Vehicle VAT

#### **Tyres**

**Fuel Type** 

Inspection

Serious Damage?

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	

#### **Features**

- Bluetooth connectionCloth seat trim
- Park assist camera
- Digital radio
- Front electric windows

#### **Photos**




















## **Condition Check**



## **Damage Photos**



1: Bumper Front Dented With Paint Damage



2: Wing osf Scratched Over 25mm Thru Paint



3: Door nsf Chipped Over 5mm



4: Door nsf Chipped Over 5mm



5: Other N/A N/A



6: Other N/A N/A



7: Bumper Rear Rusted Over 5mm



8: Other N/A N/A



9: Other N/A N/A



10: Other N/A N/A



11: Other N/A N/A



12: Other N/A N/A



13: Other N/A N/A



14: Other N/A N/A



15: Door Mirror Assy osf Scuffed (Unpainted) Over 100mm



16: Door Mirror Assy nsf Scuffed (Unpainted) Over 100mm



17: B Post os Scratched Over 25mm Thru Paint



18: Bumper Front Rusted Over 5mm



19: Centre Console Front Missing Replace

#### Interior

Carpet Condition Seat Condition	OK Average		Upholstery Condition Odour	Average -	
Engine Runs	ÿ	OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Turbo Boosting			Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	ıminated	OK
Windows		OK	Radio		OK
			Steering		OK