

# VEHICLE INSPECTION REPORT

**SH71GHV**

## Fiat Doblo CARGO 16V 1.6 MULTIJET

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 31/12/2021

Year 2021

Mileage 88,828 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V57835

Body Style Dropside L2

MOT Due 30/01/2026

CAP Clean £6,300.00

CAP Average £5,725.00

CAP Below £4,800.00

Gearbox MANUAL

Gears 5

AD-BLUE

### Tyres

NSF

NSR

OSF

OSR

Spare


## Features

- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

## Photos










## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Broken  
Replace



2: Bonnet  
Chipped  
Multiple Chips



3: Roof  
Dented  
Over 30mm



4: Wing nsf  
Dented  
With Paint Damage



5: Door nsf  
Dented  
Over 30mm



6: Door nsf  
Dented  
With Paint Damage



7: Bumper Rear  
Dented  
Over 30% Of Panel



8: Qtr Panel osr  
Cracked  
Replace





9: Carpets Front  
Holed  
Over 3mm



10: Seat Base Cover osf  
Torn  
Over 3mm



11: Seat Base Cover nsf  
Soiled  
Heavy



12: Screen Front  
Chipped  
Over 10mm

**Interior**

<b>Carpet Condition</b>	Poor	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		