

VEHICLE INSPECTION REPORT

SF16CLE

Vauxhall Movano F3500 2.3 CDTi BiTurbo ecoFLEX 136ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	18/07/2016	Body Style	Tipper Double Cab	Gearbox	MANUAL
Year	2016	Keys	2	Gears	6
Mileage	48,808 Miles Warranted	MOT Due	29/07/2026	Doors	2
Fuel Type	Diesel	CAP Clean	£5,875.00	Axle Combi	4x2
Colour	WHITE	CAP Average	£4,900.00	Rear Suspension	Steel
VIN	W0LMSP4Y2GB107459	CAP Below	£3,650.00		

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm



2: Bonnet
Dented
With Paint Damage



3: Wing osf
Dented
With Paint Damage



4: Door osf
Dented
Over 30mm



5: Door osr
Dented
Over 30mm



6: Qtr Panel osr
Dented
With Paint Damage



7: Tailgate
Dented
Over 30mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Sill ns
Dented
Over 30mm



10: Wing nsf
Dented
Over 30mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK