

VEHICLE INSPECTION REPORT

SF16CLP

Vauxhall Movano 2.3 CDTi BiTurbo ecoFLEX 136ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	27/07/2016	Body Style	Tipper Double Cab	Gearbox	MANUAL
Year	2016	Keys	1	Gears	6
Mileage	40,018 Miles Not Warranted	MOT Due	08/03/2026	Doors	2
Fuel Type	Diesel	CAP Clean	£6,175.00	Steering Combi	Standard Axle
Colour	WHITE	CAP Average	£5,150.00	Rear Suspension	Steel
VIN	W0LMSP4Y2GB107925	CAP Below	£3,825.00		

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Bonnet
Dented
With Paint Damage



4: Wing osf
Dented
With Paint Damage



5: Door osf
Dented
With Paint Damage



6: Qtr Panel osr
Dented
With Paint Damage



7: Tailgate
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Door nsf
Dented
With Paint Damage

10: Sill ns
Dented
With Paint Damage



11: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK