

VEHICLE INSPECTION REPORT

SF16CND

Vauxhall Movano 35 2.3 CDTI BiTurbo ecoFLEX H1 136ps

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present	_	
Details					
Reg. date	12/08/2016	Body Style	Tipper Double Cab	Gearbox	MANUAL
Year	2016	Keys	1	Gears	6
Mileage	26,090 Miles Warranted	MOT Due	29/07/2026	Doors	4
Fuel Type	Diesel	CAP Clean	£6,650.00	Steering Combi	Standard Axle
Colour	WHITE	CAP Average	£5,525.00	Rear Suspension	Steel
VIN	W0LMSP4Y2GB107852	CAP Below	£4,100.00	_	
Tyres NSF					
NSR					
OSF					
OSR					
Spare					

Features

- Radio/CDCloth seat trim
- Front electric windows
- Drivers airbag
- Central locking

Photos

















Condition Check



Damage Photos



1: Door osf Chipped Edge Chip



2: Wing osf Dented With Paint Damage



3: Wing osf Scratched Over 25mm Thru Paint



4: Wing nsf Dented With Paint Damage



5: Door nsf Dented With Paint Damage



6: Door osr Dented Between 10mm + 30mm

Interior

Carpet Condition Seat Condition	OK Average		Upholstery Condition OK Odour No	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engir	ne running) OK
Parking Brake		OK	No Excessive Smoking	ОК
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK

WindowsOKRadioOKSteeringOK