

# VEHICLE INSPECTION REPORT

**PJ70DJK**

## Daf CF 370

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	27/11/2020	Body Style	Box Van	Gearbox	AUTOMATIC
Year	2020	MOT Due	31/03/2026	Axle Combi	4x2
Mileage	309,126 Km Warranted	CAP Clean	£13,250.00	Rear Suspension	Steel
Fuel Type	DIESEL	CAP Average	£12,650.00	Rear Doors	Barn
Colour	WHITE	CAP Below	£10,900.00		
VIN	XLRAEM4100G318550	Cab Type	SPACE CAB		

\*WARNING LIGHTS ON DASH\* CARPET TUG CARPET WINCH, SURROUND CAMERA SYSTEM, TWIN SIDE DOOR

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
UpTo 25mm Not Thru Paint



2: Fog Lamp Surround os  
Scratched (Painted)  
UpTo 25mm Not Thru Paint





3: Bumper Front Moulding  
Scratched (Painted)  
Over 25mm Thru Paint



4: Screen Front  
Chipped  
Over 10mm



5: Grille Front  
Broken  
Replace



6: Bumper Front Moulding  
Broken  
Replace



7: Fog Lamp Surrounds  
Scratched (Painted)  
UpTo 25mm Not Thru Paint



8: Headlamp  
Broken  
Replace



9: Wing nsf  
Scratched  
UpTo 25mm Not Thru Paint



10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Door osf  
Dented  
Over 2 UpTo 10mm



13: Carpets Front  
Holed  
Over 3mm



14: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average -
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK