

# VEHICLE INSPECTION REPORT

**DW19UGK**

## Daf LF 180

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 24/07/2019

VIN XLRAEL1500L489198

Axle Combi 4x2

Year 2019

Body Style Box Van

Rear Suspension Steel

Mileage 148,300 Km Warranted

MOT Due 30/06/2026

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Column

Colour WHITE

Gearbox MANUAL

\*HEADLIGHTS IN-OP\*

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3

OSO4


### Photos







## Condition Check



## Damage Photos



1: Wing osf  
Poor Previous Repair  
Poor Colour



2: Badgedecal Front  
Missing  
Replace





3: Wing nsf  
 Scratched  
 Over 25mm Thru Paint



4: Door Mirror Assy nsf  
 Scuffed (Unpainted)  
 UpTo 100mm



5: Door nsf  
 Scratched  
 UpTo 25mm Thru Paint



6: Other  
 N/A  
 N/A



7: Other  
 N/A  
 N/A



8: Qtr Panel nsr  
 Scratched  
 Over 25mm Not Thru Paint



9: Qtr Panel osr  
 Scratched  
 Over 25mm Not Thru Paint



10: Door Mirror Assy osf  
 Scuffed (Unpainted)  
 UpTo 100mm



11: Seat Base Cover osf  
 Holed  
 Over 3mm

**Interior**

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	