

VEHICLE INSPECTION REPORT

PO13DZK

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 01/04/2013

VIN XLRAE45FF0L425133

Doors 2

Year 2013

Body Style Box Van

Axle Combi 4x2

Mileage 806,444 Km Warranted

Keys 1

Tail Lift Cantilever

Fuel Type Diesel

Service history Yes

Colour RED

Service documents Printout

* WRITTEN OFF - CORROSION CROSS MEMBER -FLOORING *
STARTS AND DRIVES

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Radio/CD
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Rusted
Over 5mm



5: Wing osf
Dented
With Paint Damage



6: B Post os
Hole
UpTo 10mm



7: Qtr Panel osr
Rusted
Over 5mm



8: Tailgate
Rusted
Over 5mm



9: Qtr Panel nsr
Rusted
Over 5mm



10: Door Mirror Assy nsf
Broken
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Poor Average		Average -	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK