

VEHICLE INSPECTION REPORT

A162357

Volvo B9R PLAXTON PANTHER

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

| | | | | | |
|-----------|--------------------------|------------|------------|-----------------|-----------|
| Reg. date | | Colour | | Cab Type | DAY CAB |
| Year | 2013 | VIN | | Gearbox | AUTOMATIC |
| Mileage | 276,607 Km Not Warranted | Body Style | Coach | Axle Combi | 4x2 |
| Fuel Type | | MOT Due | 18/09/2026 | Rear Suspension | Air |

*5% BUYERS FEE, **NOT FOR AUCTION** FOR TENDER ON FRIDAY 3RD OCTOBER* 53 SEATS + DRIVER KNEEL FUNCTION, RECLINING LEATHER SEATS, 3 PT SEAT BELTS, FOOT REST, OVERHEAD STOWAGE, REAR EMERGENCY EXIT, FULL WIDTH UNDERBODY STORAGE *MOD 654 FROM IN OFFICE*


Tyres


| | | | | |
|-------|------|------|------|------|
| NSF | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
| | OSO1 | OSO2 | OSO3 | OSO4 |

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy osf
Broken
Replace



3: Door Mirror Assy nsf
Broken
Replace



4: A Post ns
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Chipped
Multiple Chips



7: Qtr Panel nsr
Dented
With Paint Damage



8: B Post ns
Cracked
Replace



9: B Post os
Cracked
Replace



10: Qtr Panel osr
Dented
Over 30% Of Panel



11: Qtr Panel osr
Dented
Over 30% Of Panel

Interior

| | | | |
|-------------------------|----|-----------------------------|----|
| Carpet Condition | OK | Upholstery Condition | OK |
| Seat Condition | OK | Odour | - |
| Engine Runs | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | | |