Rear Doors



VEHICLE INSPECTION REPORT

FN17BPO

Daf LF 260

Serious Damage?

Inspection

		V5	Present	-	
Details					
Reg. date	29/06/2017	VIN	XLRAEL3700L462540	CAP Below	£6,625.00
Year	2017	Body Style	Curtainside	Cab Type	DAY CAB
Mileage	397,011 Km Warranted	MOT Due	30/06/2026	Gearbox	AUTOMATIC
Fuel Type	Diesel	CAP Clean	£8 975 00	Axle Combi	4x2

Plus VAT

£8,250.00

WARNING LIGHT ON DASH SURROUND CAMERA SYSTEM, FORKLIFT BRACKETS

CAP Average

Vehicle

VAT

T	y	re	S
---	---	----	---

Colour

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OS03	OSO4	

Features

Park assist camera

• Air conditioning

Photos



WHITE





Barn










Condition Check



Damage Photos



1: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



2: Fog Lamp Surround os Scuffed (Unpainted) UpTo 100mm



3: Number Plate Front Broken Replace



4: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



5: Fog Lamp Surround ns Scuffed (Unpainted) UpTo 100mm



6: Wing nsf Scratched UpTo 25mm Thru Paint



7: Other N/A N/A



8: Door Mirror Assy nsf Scuffed (Unpainted) UpTo 100mm



9: Other N/A N/A



10: Screen Front Chipped UpTo 10mm



11: Other N/A N/A



12: Door osf Dented With Paint Damage



13: Door Mirror Assy osf Scuffed (Unpainted) UpTo 100mm



14: Other N/A N/A



15: Other N/A N/A

Interior

Carpet Condition Seat Condition	OK OK		Upholstery Condition OK Odour -	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running	g) OK
			No Excessive Smoking	OK
EML light illuminated		Fault	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		ОК	Service indicator light illuminated	OK