

VEHICLE INSPECTION REPORT

PJ67LZX

Daf CF 450

Non Runner

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	20/11/2017	VIN	XLRTGM4100G183541	Axle Combi	6x2
Year	2017	Body Style	Tractor Unit	Steering Combi	Mid-Lift Steer
Mileage	1,228,088 Km Warranted	MOT Due	31/08/2026	Rear Suspension	Air
		Cab Type	SLEEPER CAB		
Fuel Type	DIESEL	Gearbox	AUTOMATIC		
Colour	RED				

NON RUNNER, CRANKS BUT DOES NOT FIRE, PARTIALLY STRIPPED

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	

Features

Air conditioning

Photos
















Condition Check



Damage Photos



1: Bumper Front Moulding Scratched (Painted)
Over 25mm Thru Paint



2: Fog Lamp Surround os Scratched (Painted) UpTo 25mm Thru Paint



3: Wing osf Chipped Multiple Chips



4: Bonnet Chipped Multiple Chips



5: Front TowEye Cvr Missing Replace



6: Bumper Front Moulding Scratched (Painted) Over 25mm Thru Paint



7: Fog Lamp Surround ns Scratched (Painted) UpTo 25mm Thru Paint



8: Door Mirror Assy nsf Scuffed (Unpainted) UpTo 100mm



9: Other N/A N/A



10: Door Mirror Assy osf Scuffed (Unpainted) UpTo 100mm



11: Other N/A N/A



12: Other N/A N/A



13: Seat Base Cover osf Holed Over 3mm



14: Other N/A N/A

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdour-

Engine Runs Fault