

# VEHICLE INSPECTION REPORT

**MF16XRD**

## Vauxhall Vivaro 2900 1.6 CDTI BITURBO 120PS ECOFLEX

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 31/03/2016

Year 2016

Mileage 90,519 Miles  
Warranted

Fuel Type Diesel

Colour SILVER

VIN W0L2F7114GS018391

Body Style Panel Van L1

MOT Due 30/03/2026

CAP Clean £3,125.00

CAP Average £2,625.00

CAP Below £1,950.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, E/ MIRRORS, TOW BAR

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Digital radio
- Drivers airbag
- Park assist camera
- Air conditioning
- Passenger airbag
- Rear parking sensor
- Front electric windows
- Central locking
- Auxiliary input socket
- Metallic Paint
- Cloth seat trim

## Photos










## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wing nsf  
Scratched  
Over 25mm Thru Paint



4: Door Mirror Assy nsf  
Broken  
Replace



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint




7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint




8: Door osr  
Dented  
Over 30mm



9: Roof  
Scratched  
Over 25mm Thru Paint




10: Qtr Panel osr  
Dented  
Over 30mm



11: Qtr Panel osr  
Dented  
With Paint Damage



12: Door osf  
Dented  
With Paint Damage



13: Door osf  
Scratched  
Over 25mm Thru Paint



14: Door osf  
Chipped  
Multiple Chips





15: Seat Base Cover osf  
Torn  
Over 3mm

16: Seat Base Cover nsf  
Soiled  
Heavy

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		