

VEHICLE INSPECTION REPORT

BK14AOL

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/03/2014

Year 2014

Mileage 706,053 Km Not Warranted

Fuel Type Diesel

Colour RED

VIN ZCFA675B502623259

Body Style Box Van

Service history Yes

Service documents Printout

MOT Due 31/12/2025

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tail Lift Cantilever

*COLLECTED AS NON RUNNER - TAIL LIFT/ FAULTS**MILEAGE DISCREPENCY ON SERVICE HISTORY*

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Rippled UpTo 30%




2: Panel Front
Chipped
Multiple Chips



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Tailgate
Rusted
Holed



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint



8: Wing osf
Cracked
Replace



9: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			