

VEHICLE INSPECTION REPORT

WM67HDF

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 27/02/2018

Year 2018

Mileage 33,364 Miles
Warranted

Fuel Type DIESEL

Colour WHITE

VIN WDB9061332N748795

Body Style Tipper MWB

MOT Due 27/02/2026

CAP Clean £6,675.00

CAP Average £5,750.00

CAP Below £4,500.00

Gearbox MANUAL

WARNING LIGHTS ON DASH

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Number Plate Front
Broken
Replace



3: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



4: Other
N/A
N/A



5: Other
N/A
N/A

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average	Average	Average	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault