

VEHICLE INSPECTION REPORT

KU64SYJ

Fuso Canter 7C15

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	07/10/2014	Body Style	Box Van	Gearbox	AUTOMATIC
Year	2014	MOT Due	31/01/2026	Axle Combi	4x2
Mileage	102,822 Km Warranted	CAP Clean	£2,250.00	Rear Suspension	Steel
Fuel Type	DIESEL	CAP Average	£2,025.00	Rear Doors	Barn
Colour	WHITE	CAP Below	£1,550.00	Tail Lift	Cantilever
VIN	TYAFEB74GRDX08441	Cab Type	DAY CAB		

SIDE BARN LOADING DOOR

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Qtr Panel osr
Dented
Over 30mm



2: Door nsr
Rusted
Over 5mm



3: Panel Rear
Scratched
UpTo 25mm Not Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK