

VEHICLE INSPECTION REPORT

LN64CFO

Mercedes-Benz Econic 2630

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	30/12/2014	Colour	WHITE	Cab Type	CREW CAB
Year	2014	VIN	WDB9560632V237928	Gearbox	AUTOMATIC
Mileage	257,080 Km Warranted	Body Style	Refuse Collector	Axle Combi	6x2
Fuel Type	DIESEL	MOT Due	31/12/2025	Rear Suspension	Steel

WING MIRRORS MISSING MIRRORS FAUN VARIOPRESS, UNIVERSAL COMPONENTS, SINGLE LIFT

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Fog Lamp Surround as
Scratched (Painted)
Over 25mm Thru Paint



2: Bumper Front
Cracked
Up To 25mm



3: Other
N/A
N/A



4: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint



5: Door Mirror Glass ns
Missing
Replace



6: Other
N/A
N/A



7: Other
N/A
N/A



8: Wheel nsr
Missing
Replace



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Wheel nsr
Missing
Replace



12: Other
N/A
N/A



13: Other
N/A
N/A



14: Wheel osr
Missing
Replace



15: Other
N/A
N/A



16: Other
N/A
N/A



17: Wheel osr
Missing
Replace



18: Other
N/A
N/A



19: Door Mirror Glass os
Missing
Replace



20: Door osf
Scratched
UpTo 25mm Thru Paint



21: Seat Base Cover osf
Holed
Over 3mm



22: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	