

# **VEHICLE INSPECTION REPORT**

**NL70CNO** 

£5,100.00 MANUAL

6

# Ford Transit Custom 2.0 EcoBlue 130ps Low Roof Trend Van

| Inspection | Vehicle |           |
|------------|---------|-----------|
|            | VAT     | Plus VAT  |
|            | V5      | To Follow |

#### **Details**

| 28/09/2020   | VIN   | WF0YXXTTGYLG48042   | CAP Below  |
|--------------|---|---|--|
| 2020         | Body Style                                  | Panel Van SWB   | Gearbox  |
| 92,142 Miles | MOT Due                                     | 27/09/2025  | Gears  |
| Warranted    | CAP Clean                                   | £6,950.00   |  |
| Diesel       | CAP Average                                 | £6,200.00   |  |
| WHITE        |   | ,   |  |
|              | 2020<br>92,142 Miles<br>Warranted<br>Diesel | 2020 Body Style 92,142 Miles MOT Due Warranted CAP Clean Diesel CAP Average | 2020         Body Style         Panel Van SWB           92,142 Miles         MOT Due         27/09/2025           Warranted         CAP Clean         £6,950.00           Diesel         CAP Average         £6,200.00 |

\*COLLECTED AS NON RUNNER- EXHAUST/FILTER ISSUES, FRONT & REAR DISCS WORN, ENGINE KNOCKING, WARNING LIGHT ON DASH\* AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres NSF

NSR

OSF

OSR Spare

**Features** 

Rear parking sensor

· Air conditioning

· Front electric windows

#### **Photos**
















# **Condition Check**



### **Damage Photos**







2: Other N/A N/A



3: Door Mirror Assy nsf Scratched (Painted) Over 25mm Not Thru Paint



4: Bumper Front Scratched UpTo 25mm Thru Paint



5: Door nsf Scratched Over 25mm Not Thru Paint



6: Door nsr Scratched Over 25mm Not Thru Paint



7: Sill ns Scratched Over 25mm Thru Paint



8: Door nsr Dented Between 10mm + 30mm



9: Bumper Rear Moulding Scratched (Painted) Over 25mm Thru Paint



10: Qtr Panel osrScratchedOver 25mm Thru Paint



11: Qtr Panel osr Scratched Over 25mm Not Thru Paint



12: Qtr Panel osr Scratched Over 25mm Thru Paint



13: Qtr Panel osr Dented Between 10mm + 30mm



14: Qtr Panel osr Dented With Paint Damage



15: Door osf Dented Between 10mm + 30mm



16: Door Mirror Assy osf Scratched (Painted) Over 25mm Thru Paint



17: Seat Base Cover osf Holed Over 3mm



18: Other N/A N/A

#### Interior

| Carpet Condition Seat Condition | Average<br>Average |       | Upholstery Condition<br>Odour | Average<br>No           |    |
|---------------------------------|--------------------|-------|-------------------------------|-------------------------|----|
| Engine Runs                     |                    | OK    | Gearbox 1st and Reverse       | e Test                  | OK |
| Brakes                          |                    | OK    | Clutch Slip Test from Sta     | tic                     | OK |
| Parking Brake                   |                    | OK    | Gearbox Static Gear Sele      | ection (engine running) | OK |
|                                 |                    |       | No Excessive Smoking          |                         | OK |
| EML light illuminated           |                    | Fault | Oil warning light illuminat   | ed                      | OK |
| Airbag light illuminated        |                    | OK    | DPF light illuminated         |                         | OK |
| ABS light illuminated           |                    | OK    | Service indicator light illu  | minated                 | OK |