

VEHICLE INSPECTION REPORT

PE17HOH

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 06/03/2017

Year 2017

Mileage 1,354,338 Miles
Warranted

Fuel Type DIESEL

Colour RED

VIN XLRTGM4100G149582

Body Style Tractor Unit

MOT Due 31/10/2025

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

COLLECTED AS NON RUNNER- GEARBOX FAULT

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



2: Fog Lamp Surround os
Scratched (Painted)
UpTo 25mm Thru Paint



3: Wing osf
Scratched
Over 25mm Thru Paint



4: Bonnet
Chipped
Multiple Chips



5: Other
N/A
N/A



6: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Not Thru Paint



7: Fog Lamp Surround ns
Scratched (Painted)
UpTo 25mm Thru Paint



8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Door Mirror Assy nsf
Broken
Replace



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



13: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK