

VEHICLE INSPECTION REPORT

FP69HFX

Daf LF 180

Inspection

•					
Serious Damage?	No	VAT	Plus VAT		
		V5	To Follow	-	
Details					
Reg. date	29/11/2019	VIN	XLRAEL1500L490382	Axle Combi	4x2
Year	2019	Body Style	Curtainside	Rear Suspension	Steel
Mileage	394,055 Km Warranted	MOT Due	30/09/2025	Rear Doors	Barn
Fuel Type	DIESEL	Cab Type	DAY CAB	-	
Colour	BLUE	Gearbox	AUTOMATIC	_	

WARNING LIGHT ON DASH ADVANCED EMERGENCY BRAKING, LANE KEEP ASSIST

Vehicle

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OS01	OS02	OS03	OSO4

Features

Navigation system

Photos
















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Screen Front Chipped UpTo 10mm



3: Door Mirror Assy nsf Broken Replace



4: Door Mirror Assy osf Scuffed (Unpainted) UpTo 100mm



5: Seat Base Cover osf Torn Over 3mm

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average -	
Engine Runs		OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Parking Brake		OK	Gearbox Static Gear Sel	ection (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		Fault	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	ıminated	OK