

VEHICLE INSPECTION REPORT

DK66KFJ

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 27/02/2017

Year 2017

Mileage 142,298 Km Warranted

Fuel Type DIESEL

Colour BLUE

VIN WMAN08ZZXHY353898

Body Style Dropside & Crane

MOT Due 31/10/2025

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

MOT INCORRECTLY RECORDED IN MILES/KM SERVICE SCHEDULE LIST & LAST CRANE TEST AVAILABLE, HMF 1420-K2 REMOTE CRANE (YEAR 2016), SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

OSO1

NSI2

OSI2

NSO2

OSO2

NSI3

OSI3

NSO3

OSO3

NSI4

OSI4

NSO4


OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Up To 25mm Thru Paint



2: Fog Lamp Surround of
Scuffed (Unpainted)
Up To 100mm



3: Fog Lamp Surround ns
Scuffed (Unpainted)
UpTo 100mm



4: Door Mirror Assy nsf
Missing
Replace



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Other
N/A
N/A



7: Bumper Rear
Rusted
Over 5mm



8: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



9: Other
N/A
N/A



10: Seat Base Cover osf
Torn
Over 3mm



11: Door Pad osf
Broken
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average		Average	
Average		-	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK