

VEHICLE INSPECTION REPORT

PE17HRP

Daf CF 440

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	15/03/2017	VIN	XLRTGM4100G150230	Axle Combi	6x2
Year	2017	Body Style	Tractor Unit	Steering Combi	Mid-Lift Steer
Mileage	1,409,868 Km Warranted	MOT Due	31/12/2025	Rear Suspension	Air
		Cab Type	SLEEPER CAB		
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	RED				

COLLECTED AS NON RUNNER - CORROSION, DIFFERENTIAL & CALLIPER ISSUES *INPUT ERROR ON MILEAGE HISTORY, MOT HISTORY INCORRECTLY RECORDED IN MILES/KM*

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OSO1	OSO2	OSO3	OSO4	

Features

- Bluetooth connection
- Manual sunroof
- · Cloth seat trim
- · Cruise control
- Air conditioning
- Auxiliary input socket
- Front electric windows
- Radio/CD
- · Central locking

Photos




















Condition Check



Damage Photos



1: Other N/A N/A



2: Bumper Front Scratched 25 to 100mm Thru Paint



3: Bumper Front Scratched Over 100mm Thru Paint



4: Qtr Panel Arch Extension ns Missing Replace



5: Qtr Panel Arch Extension os Missing Replace



6: Door osf Scratched Over 25mm Thru Paint



7: Bumper Front Scratched UpTo 25mm Thru Paint



8: Other N/A N/A

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average -	
Engine Runs	J	OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Turbo Boosting		OK	Gearbox Static Gear Sel	ection (engine running)	OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		ОК	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	ıminated	OK
Roof / sunroof		OK	Radio		OK
Windows		OK	Steering		OK