

VEHICLE INSPECTION REPORT

LN69WKG

Mercedes-Benz Actros 2546

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	04/12/2019	VIN	WDB96342320408826	Axle Combi	6x2
Year	2019	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	508,375 Km Warranted	MOT Due	30/09/2025	Rear Suspension	Air
Fuel Type	DIESEL	Cab Type	CLASSICSPACE CAB		
Colour	BLUE	Gearbox	AUTOMATIC		

WARNING LIGHT ON DASH SLIDING 5TH WHEEL, SURROUND CAMERA SYSTEM


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Fog Lamp Surround ns
Scuffed (Unpainted)
UpTo 100mm



5: Wing nsf
Chipped
Multiple Chips



6: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



7: Other
N/A
N/A



8: Door nsf
Dented
2 Or Less UpTo 10mm



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



13: Other
N/A
N/A



14: Other
N/A
N/A

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault