

VEHICLE INSPECTION REPORT

LN70XSJ

Mercedes-Benz Antos 2530

| Inspection | | Vehicle | |
|-----------------|----|---------|-----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | To Follow |

Details

| Reg. date | 27/01/2021 | VIN | WDB96302020382721 | Gearbox | AUTOMATIC |
|-----------|----------------------|-------------|-------------------|-----------------|-----------------|
| Year | 2021 | Body Style | Curtainside | Axle Combi | 6x2 |
| Mileage | 251,277 Km Warranted | MOT Due | 31/03/2026 | Steering Combi | Rear-Lift Steer |
| Fuel Type | DIESEL | Auto Trader | £18,450.00 | Rear Suspension | Steel |
| Colour | GREEN | Cab Type | DAY CAB | Rear Doors | Barn |

FORKLIFT BRACKETS, SURROUND CAMERA SYSTEM, LANE KEEP ASSIST

Tyres

| NSF | NSI1 | NSI2 | NSI3 | NSI4 | |
|-------|------|------|------|------|---|
| OSF | OSI1 | OSI2 | OSI3 | OSI4 | |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 | _ |
| | OSO1 | OSO2 | OSO3 | OSO4 | _ |

Features

Park assist camera

• Air conditioning

Photos

















Condition Check



Damage Photos



1: Fog Lamp Surround os Scuffed (Unpainted) UpTo 100mm



2: Bonnet Chipped Multiple Chips



3: Fog Lamp Surround ns Scuffed (Unpainted) UpTo 100mm



4: Door Mirror Assy nsf Scuffed (Unpainted) UpTo 100mm



5: Other N/A N/A



6: Other N/A N/A



7: Bumper Rear Rusted Over 5mm



8: Door Mirror Assy osf Scuffed (Unpainted) UpTo 100mm



9: Other N/A N/A



10: Door osf Scratched UpTo 25mm Thru Paint

Interior

| Carpet Condition Seat Condition | Average Average | | Upholstery Condition Average Odour - | |
|---------------------------------|--------------------|----|--|----|
| Engine Runs | | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | | OK | Clutch Slip Test from Static | OK |
| Parking Brake | | OK | Gearbox Static Gear Selection (engine running) | |
| | | | No Excessive Smoking | OK |
| EML light illuminated | | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | | OK | DPF light illuminated | OK |
| ABS light illuminated | | OK | Service indicator light illuminated | OK |