

VEHICLE INSPECTION REPORT

CU64FJP

Ford Transit 350 2.2 TDCI 100PS

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	17/11/2014	VIN	WF0XXXTTGXEU37826	CAP Below	£1,450.00
Year	2014	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	119,461 Miles	MOT Due	07/10/2025	Gears	6
	Warranted	CAP Clean	£2,600.00		
Fuel Type	Diesel	CAP Average	£2,100.00		
Colour	WHITE		·		

SIDE LOAD DOOR, TOW BAR, E/ MIRRORS, HEATED WINDSCREEN, DEADLOCKS (NO KEYS), POWER INVERTER, 240V SOCKETS

Tyres			
Tyres NSF			
NSR			
OSF			
OSR			
Spare			

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- · Park assist camera
- Drivers airbag
- Auxiliary input socketPassenger airbag
- Digital radio
- Central locking

Photos




















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Roof Chipped Multiple Chips



3: Door nsf Dented Over 30mm



4: Qtr Panel nsr Dented Over 30mm



5: Qtr Panel nsr Scratched Over 25mm Thru Paint



6: Qtr Panel nsr Scratched Over 25mm Thru Paint



7: Qtr Panel Moulding ns Broken Replace




8: Qtr Panel osr Dented Over 30mm



9: Qtr Panel osr Dented Over 30mm



10: Qtr Panel osr Dented With Paint Damage



11: Qtr Panel osr Dented With Paint Damage



12: Door osf Dented With Paint Damage



13: Door osf Dented Over 30mm



14: Door Mirror Assy osf Broken Replace



15: Screen Front Chipped Over 10mm



16: Door Pad osf Soiled Heavy



17: Seat Base Cover osf Holed Over 3mm



18: Seat Base Cover nsf Soiled Heavy

Interior

Carpet Condition Seat Condition	OK Poor		Upholstery Condition Odour	Poor No	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		ОК
ABS light illuminated		OK			